

Failure Prone Trees Town of Madbury

Various Circuits November 2015

Location	Pole	Diameter	Species	Cause	Wood	Perm	Other
off Huckins Rd and Long Hill Rd	326/24a-24	30"	Ash	declining	remains	Town ROW	do not leave wood on driveway
off Huckins Rd and Long Hill Rd	326/24a-24	36"	Maple	decayed leaders	remains	Town ROW	
Old Stage Road	323/1-2	26"	Pine	storm damaged	remains	Town ROW	PO notified by Town
Old Stage Road	323/6-7	36"	Pine	hollow	remains	Town ROW	PO notified by Town
Mill Hill and Old Stage	155/42						trim for clearance at corner pole
Mill Hill and Old Stage	155/42-322/12	28"	Pine	hollow base	remains	Town ROW	
Hayes Rd	303/164-163	28"	Ash	hollow	remains	Town ROW	
Hayes Rd	303/164-163	32"	Ash	declining	remains	Town ROW	
Nute Rd	321/1-2	34"	Maple	dead	remains	Town ROW	marked with yellow band
Nute Rd	321/2-3	36"	Maple	dead	remains	Town ROW	Town request, opposite side of road
Nute Rd	321/9-10	32"	Maple	dead,hollow	remains	Town ROW	
Nute Rd	321/9-10	34"	Maple	dead,hollow	remains	Town ROW	
Nute Rd	321/37-38	12"	Elm	dead	remains	Town ROW	drop dead statue
Nute Rd	321/37-38	18"	Maple	heavy lean	remains	Town ROW	
Nute Rd	321/37-38	20"	Maple	twin lead	remains	Town ROW	
Nute Rd	321/40-41	10"	Elm	dead	remains	Town ROW	
Nute Rd	321/50-51	12"	Maple	hollow	remains	Town ROW	
Nute Rd	321/50-51	8"	Maple	soft base	remains	Town ROW	
Nute Rd	321/51-52	8"	Maple	heavy lean	remains	Town ROW	