

ROCKINGHAM COUNTY CONSERVATION DISTRICT

110 North Road, Brentwood, NH 03833-6614 Tel: 603-679-2790 • Fax: 603-679-2860 www.rockinghamccd.org

11 December 2013

Eric Fiegenbaum, Administrative Assistant Town of Madbury 13 Town Hall Road Madbury, NH 03820

RE: Fra

Frank Catapano 38 Huckins Road Tax map/lot: 2/20 RCCD #MA2-20-L13

Dear Mr. Fiegenbaum;

On this date I witnessed 20 test pits for a proposed residential subdivision. The designer representing the owner was Jim Gove of Gove Environmental Services.

The following features were observed:

	Seasonal High		Total	
Test Pit	Water Table	Bedrock	Depth	Pass/Fail
FC1	26"	yes	48"	fail
FC2	28"	no	76"	pass
FC3	22"	no	63"	fail
FC4	25"	no	72"	pass
FC5	25"	yes	42"	fail
FC6	24"	yes	67"	pass
FC7	24"	no	72"	pass
FC8	13"	yes	39"	fail
FC9	23"	yes	41"	fail
FC10	13"	yes	35"	fail
FC11	21"	no	68"	fail
FC12	20"	no	67"	fail
FC13	24"	no	72"	pass
FC14	22"	no	70"	fail
FC15	24"	no	74"	pass
FC16	18"	no	70"	fail
FC17	24"	no	69"	pass
FC18	20"	no	64"	fail
FC19	19"	no	69"	fail
FC20	26"	no	72"	pass

Test pits FC2, FC4, FC6, FC7, FC13, FC15, FC17, and FC20 meet town and state soil requirements for wastewater disposal. Whether the test pits meet setback requirements and the acceptability of the 4,000 square foot reserve area can be determined after the test pits are survey located and presented on the subdivision plan.

The remaining test pits did not meet either the locally required minimum 24 inches to seasonal high water table, or 60 inches to bedrock, or both.

A test pit field summary is attached.

Sincerely,

Michael Cuomo

NH Certified Soil Scientist #6

Widral Cums

NH Certified Wetland Scientist #4

681

NH Designer #788

Cynthia W. Smith

Chairman, Board of Directors