

ROCKINGHAM COUNTY CONSERVATION DISTRICT

110 North Road, Brentwood, NH 03833-6614 Tel: 603-679-2790 • Fax: 603-679-2860 www.rockinghamccd.org

7 July 2021

Eric Fiegenbaum, Administrative Assistant Town of Madbury 13 Town Hall Road Madbury, NH 03820

RE:

DiBerto

326 Knox Marsh Road Tax map/lot: 8/1G RCCD #MA8-1-G L21

Dear Mr. Fiegenbaum;

On this date RCCD staff witnessed eight test pits for a proposed residential subdivision to create one new lot. The designer representing the owner was Chris Berry.

The following features were observed:

		Seasonal High	Total		
Te	est Pit	Water Table	Depth	Bedrock	Pass/Fail
1		13"	44"	no	fail
2		24"	60"	no	pass
3		20"	36"	yes	fail
4		25"	72"	no	pass
5		18"	40"	no	fail
6		24"	60"	yes	pass
7		27"	60"	no	pass
8		28"	72"	no	pass

Test pits 2, 4, 6, 7, and 8 meet town and state soil and slope requirements for wastewater disposal.

Test pit 3 does not meet local soil requirements because bedrock was found less than 60" from the surface.

Test pits 1, 3, and 5 do not meet local soil requirements because the seasonal high water table was found less than 24" from the surface.

A test pit field summary is attached.

Sincerely,

Michael Cuomo

NH Certified Soil Scientist #6

Widral Cems

NH Certified Wetland Scientist #4

NH Designer #788