



Fraggle Rock Environmental Services
Damon E. Burt, CWS, CPESC
38 Garland Road, Strafford NH 03884
603-969-5574
FRenvironmental@gmail.com

February 11, 2021

Wetland Review Report

Tillman
Mill Hill Road
Madbury NH 03820
Tax Map 5; Lot 16

Fraggle Rock Environmental performed review of site for wetlands on December 2, 2020 based on the following standards:

Wetland Delineation/Review Standards

- Corps of Engineers Wetland Delineation Manual, Technical Report 4-87-1, (January, 1987)
- U.S. Army Corps of Engineers, Regional Supplement to the Corps of Engineers Wetland Delineation Manual: Northcentral and Northeast Region, Version 2.0, U.S. Army Engineer Research and Development Center, 3909 Halls Ferry Road, Vicksburg, MS 39180-6199, January 2012, ERDC/EL TR-12-1
- Cowardin, Lewis M., Golet, Francis C. and LaRoe, Edward T, Classification of Wetlands and Deepwater Habitats of the United States, USFWS, Dept. of the Interior, Wash. D.C., 1979.
- Field Indicators of Hydric Soils in the United States A Guide for Identifying and Delineating Hydric Soils, Version 8.1, 2017 (Including corrections to version 8.0, 2016, on pages 21, 25, and 34)
- New England Hydric Soils Technical Committee. 2017 Version 4, Field Indicators for Identifying Hydric Soils in New England. New England Interstate Water Pollution Control Commission, Lowell, MA
- U.S. Army Corps of Engineers 2016. National Wetland Plant List/State List, Version 3.3

Findings

No jurisdiction wetlands were noted on the property.

Sincerely,

Damon E. Burt, CWS, CPESC
Fraggle Rock Environmental Services
NH Certified Wetland Scientist
Certified Professional in Erosion and Sediment Control