

Fraggle Rock Environmental Services Damon E. Burt, CWS, CPESC 38 Garland Road, Strafford NH 03884 603-969-5574

FRenvironmental@gmail.com

April 16, 2019

Wetland Review - Very Poorly/Poorly Drained

Stephen H. Smith Hayes Road Subdivision – Tax Map 5, Lot 8 Madbury, NH Tax Map 5, Lot 8-M1 & M2

Fraggle Rock Environmental performed review of site for wetlands on April 13, 2019, based on the following standards:

Wetland Delineation/Review Standards

- Corps of Engineers Wetland Delineation Manual, Technical Report 4-87-1, (January, 1987)
- U.S. Army Corps of Engineers, Regional Supplement to the Corps of Engineers Wetland Delineation Manual: Northcentral and Northeast Region, Version 2.0, U.S. Army Engineer Research and Development Center, 3909 Halls Ferry Road, Vicksburg, MS 39180-6199, January 2012, ERDC/EL TR-12-1
- Cowardin, Lewis M., Golet, Francis C. and LaRoe, Edward T, Classification of Wetlands and Deepwater Habitats of the United States, USFWS, Dept. of the Interior, Wash. D.C., 1979.
- Field Indicators of Hydric Soils in the United States A Guide for Identifying and Delineating Hydric Soils, Version 8.1, 2017 (Including corrections to version 8.0, 2016, on pages 21, 25, and 34)
- New England Hydric Soils Technical Committee. 2017 Version 4, Field Indicators for Identifying Hydric Soils in New England. New England Interstate Water Pollution Control Commission, Lowell, MA
- U.S. Army Corps of Engineers 2016. National Wetland Plant List/State List, Version 3.3

Findings

Fraggle Rock Environmental reviewed wetlands located at Tax Map 5, Lot 8 - M1 & M2 to determine if the wetlands are classified as Poorly Drained or Very Poorly Drained.

Both wetlands located on Tax Map 5, Lot 8-M1 & M2 can be classified as having a drainage class of Poorly Drained for setback purposes.

Sincerely,

Damon E. Burt, CWS, CPESC

Fraggle Rock Environmental Services

Jamon E. Burt

NH Certified Wetland Scientist

Certified Professional in Erosion and Sediment Control